

ExpertEase™ Software Version 14.0

System Requirements

Minimal Requirements:

- Pentium IV CPU or Intel-based Macintosh system (booted in Windows under Boot Camp for using the advanced volume rendering)
- Windows XP/Vista/7 (64-bit compatible)
Citrix servers and Unix systems are not supported
- 1 GB of RAM, 2 GB of free hard disk space (assumes cases are deleted daily & only 3 cases scanned per day)
- Graphics card with full DirectX9.0c compliance, HW vertex processing, Shader Model 3.0 support and 128 MB of video memory for using the advanced volume rendering
- Microsoft Internet Explorer 7.0
- Internet connection for ordering drill guides on-line, communication via DentalPlanit®, automatic license renewal and automatic updates

Recommended:

- Intel® Core™ i5 or above
- Windows Vista/7
- 4 GB of RAM (or more), 20 GB of free hard disk space
- Diagnostic monitor
- ATI or NVIDIA graphics card with full DirectX 10.1 compliance and 1 GB of video memory
- Scroll mouse
- Microsoft Internet Explorer 8.0
- Internet connection

Distributor:

Friadent GmbH · Steinzeugstraße 50
68229 Mannheim/Germany
Phone +49 621 4302-1288
Fax +49 621 47 13 06
e-mail: info@friadent.de

Manufacturer:

Materialise Dental NV · Technologielaan 15
3001 Leuven · Belgium
Phone +32 16 39 66 20
Fax +32 16 39 66 22
e-mail: simplant@materialise.be